


FIG. 1



Overheated solution, precipitation zone

FIG. 2a

FIG. 2b

Metal




FIG. 3